

Johnson Outboards 1969- Later

Johnson Outboards 1969- Later

Model	Hp	Year	Model	Hp	Year	Model	Hp	Year	Model	Hp	Year	Model	Hp	Year	Model	Hp	Year			
1R69	1.5	1969	4W76	4	1976	J10SELCI	9.9	1981	J20CRCN-J20CRLCN	20	1982	33R69-33RL69	33	1969	J50BECN-J50BELCS	50	1980	J70TLCN	70	1982
1R70	1.5	1970	4W77	4	1977	J10SELCS	9.9	1982	J20CRCR-J20CRLCR	20	1984	33R70-33RL70	33	1970	J50BECT-J50BELCT	50	1983	J70TLCR	70	1984
J2RCI	2	1981	4W78	4	1978	J10SELCS	9.9	1980	J20CRCT-J20CRLCT	20	1984	J35BACR-J35BALCR	35	1984	J50ECS-J50ELCS	50	1984	J70TLCT	70	1983
J2RCR	2	1982	4W79	4	1979	J10SELCT	9.9	1983	20R69-20RL69	20	1969	J35ECI-J35ELCI	35	1981	J50TELCR	50	1984	70EL76	70	1976
J2RCS	2	1984	J5RCI-J5RLCI	4.5	1981	10E74-10EL74	9.9	1974	20R70-20RL70	20	1970	J35ECN-J35ELCN	35	1982	J50TELCT	50	1983	70EL77	70	1977
J2RCS	2	1980	J5RCN-J5RLCN	4.5	1982	10E75-10EL75	9.9	1975	20R71-20RL71	20	1971	J35ECR-J35ELCR	35	1984	J50TLCR	50	1984	70EL78	70	1978
J2CT	2	1983	J5RCS-J5RLCS	4.5	1980	10E75-10EL76	9.9	1976	20R72-20RL72	20	1972	J35ECS-J35ELCS	35	1980	50ES71-50ESL71	50	1971	70EL79	70	1979
2R71	2	1971	J5RHCI-J5RHLCI	4.5	1981	10E77-10EL77	9.9	1977	20R73-20RL73	20	1973	J35CT-J35ELCT	35	1983	50ES72-50ESL72	50	1972	70ESLR74	70	1974
2R72	2	1972	J5RHCN-J5RHLCN	4.5	1982	10E78-10EL78	9.9	1978	J25BACR-J25BALCR	25	1984	J35RCI-J35RLCI	35	1981	50ES73-50ESL73	50	1973	70ES74-70ESL74	70	1974
2R73	2	1973	J5RHCS-J5RH LCS	4.5	1980	10E79-10EL79	9.9	1979	J25BECR-J25BELCR	25	1984	J35RCN-J35RLCN	35	1982	50ES74-50ESL74	50	1974	70ES75-70ESL75	70	1975
2R74	2	1974	J5RHCT-J5RH LCT	4.5	1983	10R74-10RL74	9.9	1974	J25BFRCR-J25BF LCR	25	1984	J35RCR-J35RLCR	35	1984	50ES75-50ESL75	50	1975	J75ECN-J75ELCN	75	1982
2R75	2	1975	J5BFRCR-J5BF LCR	5	1984	10R75-10RL75	9.9	1975	J25ECI-J25ELCI	25	1981	J35RCS-J35RLCS	35	1980	50R72-50RL72	50	1972	J75ECR	75	1984
2R76	2	1976	J6BACR-J6BALCR	6	1984	10R76-10RL76	9.9	1976	J25ECN-J25ELCN	25	1982	J35RCT-J35RLCT	35	1983	50R73-50RL73	50	1973	J75ECT-J75ELCT	75	1983
2R77	2	1977	J6BFCR-J6BF LCR	6	1984	10R77-10RL77	9.9	1977	J25ECR-J25ELCR	25	1984	J35TELCR	35	1984	50R77-50RL77	50	1977	J75ELCT	75	1984
2R78	2	1978	J6RCR-J6RLCR	6	1984	10R78-10RL78	9.9	1978	J25ECT-J25ELCT	25	1983	J35TELC	35	1983	50R78-50RL78	50	1978	J75ERCI	75	1981
2R79	2	1979	J6SLCR	6	1984	10R79-10RL79	9.9	1979	J25RCI-J25RLCI	25	1981	35E76-35EL76	35	1976	50R79-50RL79	50	1979	J75ERCS	75	1980
J4BRCI-J4BRLCI	4	1982	6R69-6RL69	6	1969	10SEL78	9.9	1978	J25RCN-J25RLCN	25	1982	35E77-35EL77	35	1977	J55RCH-J55RLCN	55	1982	J75ERLCI	75	1981
J4BRCN-J4BRLCN	4	1982	6R70-6RL70	6	1970	10SEL79	9.9	1979	J25RCR-J25RLCR	25	1984	35E78-35EL78	35	1978	J55RCI-J55RLCI	55	1981	J75ERLCS	75	1980
J4BRCR-J4BRLCR	4	1984	6R71-6RL71	6	1971	J10BACR-J10BALCR	10	1984	J25RCS-J25RLCS	25	1980	35E79-E79EL79	35	1979	J55CT-J55RLCT	55	1983	J75TLCN	75	1982
J4BRHCI-J4BRHLCI	4	1981	6R72-6RL72	6	1972	J10ELCR	10	1984	J25RCT-J25RLCT	25	1983	35R76-35RL76	35	1976	J55RLCS	55	1980	J75TLCT	75	1984
J4BRHCN-J4BRHLCN	4	1982	6R73-6RL73	6	1973	J10RCR-J10RLCR	10	1984	J25TECI-J25TELCI	25	1981	35R77-35RL77	35	1977	55ES69	55	1969	J75TLCT	75	1983
J4BRHCR-J4BRHLCR	4	1984	6R74-6RL74	6	1974	J10SELCR	10	1984	J25TECN-J25TELCN	25	1982	35R78-35RL78	35	1978	55E76-55EL76	55	1976	J75TRLCI	75	1981
J4BRHCT-J4BRHLCT	4	1983	6R75-6RL75	6	1975	J15BACR-J15BALCR	15	1984	J25TECR-J25TELCR	25	1984	35R79-35RL79	35	1979	55E77-55EL77	55	1977	J75TRLCS	75	1980
J4RDRCR-J4RDRLCR	4	1984	6R76-6RL76	6	1976	J15ECI	15	1981	J25TECS-J25TELCS	25	1980	J40ECR-J40ELCR	40	1984	55E78-55EL78	55	1978	75ER76-75ELR76	75	1976
J4RDHCR-J4RDHLCR	4	1984	6R77-6RL77	6	1977	J15ECN	15	1982	J25TECT-J25TELCT	25	1983	J40TACR-J40TALCR	40	1984	55E79-55EL79	55	1979	75ER77-75ELR77	75	1977
J4RLCS	4	1980	6R78-6RL78	6	1978	J15ECR-J15ELCR	15	1984	25E72-25EL72	25	1972	J40TELCR	40	1984	55R79-55RL79	55	1979	75ER78-75ELR78	75	1978
J4WCI	4	1981	6R79-6RL79	6	1979	J15ECS-J15ELCS	15	1980	25E73-25EL73	25	1973	40ES69-40ESL69	40	1969	J60ECI-J60ELCI	60	1981	75ER79-75ELR79	75	1979
J4WCS	4	1980	J8RCI-J8RLCI	7.5	1981	J15ECT-J15ELCT	15	1983	25E74-25EL74	25	1974	40ES70-40ESL70	40	1970	J60ECN-J60ELCN	60	1982	75ESR75-75ESLR75	75	1975
J5RHCR	4	1984	J8RCN-J8RLCN	7.5	1982	J15RCI-J15RLCI	15	1981	25E75-25EL75	25	1975	40E69-40EL69	40	1969	J60ECR-J60ELCR	60	1984	J85MLCS	85	1980
4R69-4RL69	4	1969	J8RCS-J8RLCS	7.5	1980	J15RCN-J15RLCN	15	1982	25E76-25EL76	25	1976	40E70-40EL70	40	1970	J60ECS-J60ELCS	60	1980	J85TLCN-J85TLXCS	85	1980
4R70-4RL70	4	1970	J8RCT-J8RLCT	7.5	1983	J15RCR-J15RLCR	15	1984	25E77-25EL77	25	1977	40E71-40EL71	40	1971	J60ECT-J60ELCT	60	1983	85EL76	85	1976
4R71-4RL71	4	1971	J8SRLCN	7.5	1982	J15RCS-J15RLCS	15	1980	25E78-25EL78	25	1978	40E72-40EL72	40	1972	J60TLCI	60	1981	85EL77	85	1977
4R72-4RL72	4	1972	J8SRLCT	7.5	1983	J15RCT-J15RLCT	15	1983	25E79-25EL79	25	1979	40E73-40EL73	40	1973	J60TLCN	60	1982	85ESL69	85	1969
4R73-4RL73	4	1973	J8BACR-J8BALCR	8	1981	15E74-15EL74	15	1974	25R69-25RL69	25	1969	40E74-40EL74	40	1974	J60TLCR	60	1984	85ESL70	85	1970
4R74-4RL74	4	1974	J8RCR-J8RLCR	8	1984	15E75-15EL75	15	1974	25R70-25RL70	25	1970	40E75-40EL75	40	1975	J60TLCT	60	1983	85ESL71	85	1971
4R75-4RL75	4	1975	J8SRLCR	8	1984	15E76-15EL76	15	1976	25R71-25RL71	25	1971	40E76-40EL76	40	1976	60ES70-60ESL70	60	1970	85ESL72	85	1972
4R76-4RL76	4	1976	9R69-9RL69	9.5	1969	15E77-15EL77	15	1977	25R72-25RL72	25	1972	40R69-40RL69	40	1969	60ES71-60ESL71	60	1971	85ESL73	85	1973
4R77-4RL77	4	1977	9R70-9RL70	9.5	1970	15E78-15EL78	15	1978	25R73-25RL73	25	1973	40R70-40RL70	40	1970	65ESLR72	65	1972	85ESL74	85	1974
4R78-4RL78	4	1978	9R71-9RL71	9.5	1971	15E79-15EL79	15	1979	25R74-25RL74	25	1974	40R71-40RL71	40	1971	65ESR73-65ESLR73	65	1973	85ESL75	85	1975
4R79-4RL79	4	1979	9R72-9RL72	9.5	1984	15R74-15RL74	15	1974	25R75-25RL75	25	1975	40R72-40RL72	40	1972	65ES72-65ESL72	65	1972	85ETLR76	85	1976
4W69	4	1969	9R73-9RL73	9.5	1973	15R75-15RL75	15	1975	25R76-25RL76	25	1976	40R73-40RL73	40	1973	65ES73-65ESL73	65	1973	85ETLR77	85	1977
4W70-4WL70	4	1970	J10ECS-J10ELCS	9.9	1980	15R76-15RL76	15	1976	25R77-25RL77	25	1977	40R74-40RL74	40	1974	J70ELCI	70	1981	85ETLR78	85	1978
4W71-4WL71	4	1971	J10ELCI	9.9	1981	15R77-15RL77	15	1977	25R78-25RL78	25	1978	40R75-40RL75	40	1975	J70ELCN	70	1982	85ML78	85	1978
4W72	4	1972	J10ELCN	9.9	1982	15R78-15RL78	15	1978	25R79-25RL79	25	1979	40R76-40RL76	40	1976	J70ELCR	70	1984	85ML79	85	1979
4W73	4	1973	J10RCN-J10RLCN	9.9	1982	15R79-15RL79	15	1979	J30ECR-J30ELCR	30	1984	J50BECI-J50BELCI	50	1981	J70ELCS	70	1980	85TL79	85	1979
4W74	4	1974	J10RCS-J10RLCS	9.9	1980	J20BFRCR-J20BF LCR	20	1984	33E69-33EL69	33	1969	J50BECN-J50BELCN	50	1982	J70ELCT	70	1983	85TXLR77	85	1977
4W75	4	1975	J10RCT-J10RLCT	9.9	1983	J20BACR-J20BILCR	20	1984	33E70-33EL70	33	1970	J50BECR-J50BELCR	50	1984	J70TLCI	70	1981	85TXLR78	85	1978

